

# VIGNANA BHARAT LABORATORIES

D.No. 1-4-227/2, Narasimha Enclave Opposite Street, Left Side 4th Building,  
R.T.C. Work Shop Road, Bhavani Puram, VIJAYAWADA - 520 012. Cell : 93923 57666.

Ref :

Date : .....

## TEST REPORT

Our Ref:	OCT-38/OCTOBER /2021	Issued To:
Reporting Date:	26-10-2021	DON BOSCO SCHOOL GUNTUPALLI REPRESENTED BY ITS SECRETARY FATHAR NATHAN
Collected On:	25-10-2021	
Received on:	26-10-2021	
Sample Particulars:	SOURCE: BORE WATER	

	PHYSICAL PARAMETERS / UNITS	RESULT	IS: 14543 : PACKAGED DRINKING WATER DESIRABLE LIMIT	IS: 10500: MAX. PERMISSIBLE LIMIT
1	Colour	"0" Hazen units	"2" Hazen units	25
2	Odour (agreeable/not agreeable)	Agreeable	AGREEABLE	UNOBJECTION
3	Taste (agreeable/not agreeable)	Agreeable	AGREEABLE	AGREEABLE
4	Turbidity (NTU)	0 NTU	2	10
5	PH @31.4Deg .C	7.43	6.0 to 8.5	6.0 to 8.5
6	Total Dissolved Solids (mg/l) through meter reading	835	500	2000

## CHEMICAL PARAMETERS/UNITS

1	Alkalinity to Phenolphthalein as CaCO <sub>3</sub> (mg/l)	NIL	-----	-----
2	Alkalinity to Methyl orange as CaCO <sub>3</sub> (mg/l)	275.2	200	600
3	Total Hardness as CaCO <sub>3</sub> (mg/l)	501.4	-----	600
4	Calcium as Ca (mg/l)	78.48	75	200
5	Magnesium as Mg (mg/l)	74.16	30	100
6	Chloride as Cl (mg/l)	408.0	200	1000
7	Sulphate as SO <sub>4</sub> (mg/l)	140	200	400
8	Nitrite as NO <sub>2</sub> (mg/l)	0.002	0.02	-----
9	Ammonical Nitrogen	NIL	-----	-----
10	Fluoride as F (mg/l)	0.8	1.0	1.5
11	Residual free chlorine	NIL	0.2	-----
12	Silica	26	-----	-----
13	Iron as Fe	0.6	0.1	1.0

NOTE: SAMPLE IS NOT DRAWN BY V.B.L

for VIGNANA BHARAT LABORATORIES



AUTHORISED SIGNATURE

Principa!

DON BOSCO SCHOOL  
GUNTUPALLI - 521 241  
Krishna Dt., (A.P.)

Re. No.SPL/1220.

IBRAHIMPATNAM,

Date: 08/10/2021.

**SANITARY CERTIFICATE**

This is to certify that the Sanitary Inspector of Ibrahimpatnam mandal has inspected the DON BOSCO SCHOOL (Reg.No.3433/A5/2021), at GUNTUPALLI, Ibrahimpatnam mandal, Krishna District, certify that the accommodation provided to the students in each class is sufficient. The school is properly ventilated and lighted. The building is maintained with substantial repair and the School premises in and around is maintained neat and clean. The supply of drinking water is wholesome and the toilet facilities are adequate. Sanitation is maintained and all other aspects are satisfactory.

Assistant Medical Officer of Health

MEDICAL OFFICER  
PRIMARY HEALTH CENTRE  
IBRAHIMPATNAM

To,  
The Correspondent,  
Don Bosco School,  
The Guntupalli Don Bosco Society,  
GUNTUPALLI -521 241,  
Ibrahimpatnam mandal,  
Krishna District.

Principal  
DON BOSCO SCHOOL  
GUNTUPALLI - 521 241  
Krishna Dt., (A.P.)